IMPORTANT TEST AREA: The surface type or condition may be unknown before the paint is removed. To ensure satisfactory results, it is advised a small test area be stripped before beginning a project.

APPLICATION: Apply Marine Safety Strip with a brush about 1/8" (3 mm) thick (thick enough so that you cannot see thru the product). Dwell time should be between 4-8 hours depending on the thickness of the varnish or paint being removed. Test patches will determine correct time frame. Remove by sliding spatula or putty knife under paste, easing varnish or paint and paste from the surface. Surface should then be cleaned down with Marine Strip Cleaner or Mineral Spirits and a non-abrasive scrubbing pad and then wiped down with a sponge or cloth.

SENSIBLE PRECAUTIONS: Not for internal consumption. Note that some people's skin may be sensitive to some of the chemicals, so we suggest that you wear rubber gloves.

CONTENTS HARMFUL. FUMES HARMFUL. MAY IRRITATE EYES AND SKIN.

Do not mix with any other product or chemical. Do not get in eyes or on skin or clothing. Do not breathe vapours.

KEEP OUT OF REACH OF CHILDREN.

Wear rubber gloves. Use only in a well-ventilated area.

FIRST AID TREATMENT: Contains dimethyl glutarate, and dimethyl adipate. If swallowed, call a Poison Control Center or doctor immediately. DO NOT INDUCE VOMITING. IF IN EYES, OR ON SKIN, RINSE WELL WITH WATER FOR 15 MINUTES. IF ON CLOTHES, REMOVE CLOTHES. IF BREATHED IN, MOVE PERSON INTO FRESH AIR.

Technical Help Line: 1-212-869-6350

Always Recycle! 😂

West Marine®

500 Westridge Dr. Watsonville, CA 95076 Made in USA

www.westmarine.com

