

UC128-OBF

| ENGINE | MODEL | YEAR | CILINDER | P. NO. |
|----------------------|--|--------------|---------------|-------------|
| Mercury® Mariner® | 75-90-115-125 Optimax 2 Stroke | 2004-to date | UC128-OBF/3 | 39967 T |
| | 135-150-175 Optimax 2 Stroke | 1999-to date | UC128-OBF/1 | 39423 Z |
| | 200-225-250 Optimax 2 Stroke | 1999-to date | UC128-OBF/1 | 39423 Z |
| | RACING 300 Optimax 2 Stroke | 1999-2011 | UC128-OBF/1 | 39423 Z |
| | 100-115 EFI 4 Stroke | 2007-to date | UC128-OBF/1 | 39423 Z |
| | 115-125-150 EFI 2 Stroke | 1990-2007 | UC128-OBF/1 | 39423 Z |
| | 225-250 EFI 2 Stroke | 2000-2007 | UC128-OBF/1 | 39423 Z |
| | 250 Saltwater EFI 4 Stroke | 2007-2011 | UC128-OBF/1 | 39423 Z |
| | 135 Verado L4 4 Stroke | 2004-2006 | UC128-OBF/1 | 39423 Z |
| | 150-175-200 Verado L4 4 Stroke | 2004-to date | UC128-OBF/1 | 39423 Z |
| Evinrude® | E75-E90 2 Stroke | 2004-to date | UC128-OBF/2 | 39966 R |
| | E115-E130-E135 2 Stroke V4 | 1995-to date | UC128-OBF/2 | 39966 R |
| | E150-E175-E200 2 Stroke V6 | 1995-to date | UC128-OBF/2 | 39966 R |
| | E200 HO- E225-E250 2 Stroke V6 | 1995-to date | UC128-OBF/2 | 39966 R |
| Yamaha® | 75C-90 2 Stroke | 1998-2008 | UC128-OBF/2 | 39966 R |
| | 115C-130B 2 Stroke | 1990-2008 | UC128-OBF/2 | 39966 R |
| | 150F-200F-250G 2 Stroke | 1996-2007 | UC128-OBF/2 | 39966 R |
| | 150 HPDI VMAX 2 Stroke | 2000-2008 | UC128-OBF/2 | 39966 R |
| | 175-200-225-250-300 HPDI VMAX 2 Stroke | 2000-2008 | UC128-OBF/2 | 39966 R |
| | F70 4 Stroke | 2010-to date | UC128P-OBF/1 | 40106U |
| | F90-F100-F115-F150 EFI 4 Stroke | 1999-2007 | UC128-OBF/1 | 39423 Z |
| | F200-F225-F250 4 Stroke | 2002-2007 | UC128-OBF/2 | 39966 R |
| | F115-F150 | 2004-to date | UC128-OBF/1 | 39423 Z |
| | F200-F225-F250-F300 4 Stroke | 2006-to date | UC128-OBF/2 | 39423 Z |
| Honda® | F350 4 Stroke | 2008-to date | see UC128-SVS | SilverSteer |
| | BF75-90 4 Stroke | 1995-to date | UC128-OBF/1 | 39423 Z |
| | BF115D | 1998-2009 | UC128-OBF/3 | 39967 T |
| | BF115A | 2009-to date | UC128-OBF/1 | 39423 Z |
| | BF130A | 1998-2005 | UC128-OBF/3 | 39967 T |
| | BF135-150 4 Stroke | 2005-to date | UC128-OBF/1 | 39423 Z |
| | BF90-BF150 V-TEC 4 Stroke | 2008-to date | UC128-OBF/1 | 39423 Z |
| Suzuki® | BF175-200-225 4 Stroke | 2001-to date | UC128-OBF/1 | 39423 Z |
| | DF70-80-90 4 Stroke | 1998-to date | UC128-OBF/2 | 39966 R |
| | DF100-115-140 4 Stroke* | 1998-2008 | UC128-OBF/1* | 39423 Z |
| | DF100-115-140 4 Stroke new model | 2008-to date | UC128-OBF/1 | 39423 Z |
| | DF150-175 4 Stroke | 2006-to date | UC128-OBF/1 | 39423 Z |
| Tohatsu® | DF200-DF225-DF250-DF300 | | UC128-OBF/2 | 39966 R |
| | 115-120-140 2 Stroke | 2004-to date | UC128-OBF/2 | 39966 R |
| Selva® | 70-90-115 TLDI 4 Stroke | 2004-2011 | UC128-OBF/1 | 39423 Z |
| | 80 Portofino/Tigershark 2 Stroke | 1995-to date | UC128-OBF/1 | 39423 Z |
| Johnson® | 150 White Shark 2 Stroke | | | |
| | 100EFI Marlin -115 EFI Narwhal- | 2001-2007 | UC128-OBF/2 | 39966 R |
| | 150EFI Killer Whale 4 Stroke | 2000-to date | UC128-OBF/1 | 39423 Z |
| Johnson® | BJ90-115-140 4 Stroke | 2001-2007 | UC128-OBF/1 | 39423 Z |
| | J90-115 V4 2 Stroke | 1995-2007 | UC128-OBF/2 | 39966 R |
| | J150-175 V6 2 Stroke | 1995-2007 | UC128-OBF/2 | 39966 R |
| | J200-225 V6 4 Stroke | 2004-2007 | UC128-OBF/2 | 39966 R |

***NOTE:**

Suzuki® engines built from 1998 to 2008 installing UC128-OBF/1 cylinder require optional **KIT SU** - 41954W.
For higher horsepower applications, high performance SilverSteer™ cylinder is recommended.

WARNING

These recommendations should be used as a general reference only.

Final selection should be made with the assistance of a qualified installation technician.

For any further information please contact our Technical Service.